

Cadence - Windows

Care 2

MAINTENANCE PROCEDURES FOR PRIVACY FABRICS

- Machine washable up to 160°F, gentle cycle. Do not exceed 160°F
- Line dry immediately after machine washing.
- Tumble-drying is also permissible at low heat setting. Do not overstuff dryer load.
- Remove Promptly from dryer after completion of drying cycling.
- If needed, press with commercial steam iron or flat bed press at low temperatures suitable for synthetic materials.
- It may be necessary to adapt these instructions to the specific conditions of the laundry, and equipment.
- Dry cleaning is permissible. Use only commercial dry cleaners.