

Textile Testing

553 76th Street - Byron Center, MI 49315 Phone: 616.559.6123 Fax: 616.559.6119

Report Number:37473

Date: 10-29-09

For the Account Of:

Carnegie Fabrics

110 North Center Avenue Rockville Center, NY 11570

Contact:

Charles Griffin

Client's Identification:

ALLURE 6468

Test Performed

California Technical Bulletin 117, Section E (CPSC 16 CFR 1610 - CS 191-53) Upholstery

CARNEGIE

Fabrics

TEST DATA

□ Raised Surface

	Flame Spread Warp Face	<u>Flame Spread</u> <u>Warp Back</u>
Specimen	(seconds)	(seconds)
. 1	DNI	
2	DNI	
. 3	DNI	
, 4		DNI
5		DNI

	Flame Spread	<u>Flame Spread</u>
	Fill Face	Fill Back
Specimen	(seconds)	(seconds)
1	DNI	··
2	DNI	
3	DNI	
4		DNI
5		DNI

ABBREVIATIONS USED

DNI Did not ignite when exposed to test ignition source

IBE Ignited but extinguished before burning through stop cord

SF Surface flash only; stop cord not burned & no burning/charring/fusing of the base fabric

TSF Timed surface flash; stop cord burned, but no burning/charring/fusing of the base fabric

ACCEPTANCE CRITERIA

- 1. With nap Minimum flame spread of any individual specimens shall be 7 seconds.
- 2. Without nap Minimum flame spread of any individual specimens shall be 3.5 seconds.

CONCLUSION

Based on the above Results and Acceptance Criteria, the item tested:

Does Not Comply

CERTIFICATION I certify that the above results were obtained after testing specimen in accordance with the procedures and equipment specified by the stangalid stated above.

Authorized Signature-MB