Carnegie

Curve

Care 13

MAINTENANCE
INSTRUCTIONS FOR
BAUMANN TREVIRA
CS WALLCOVERING

Cleaning Code WS: Clean with mild detergent shampoo, foam, or water free solvents. Do not saturate with liquids.

- All stains should be treated blotted out as soon as possible with clean water, and a soft absorbent cloth (white) or sponge. A mild detergent solution with warm water or water-free solvent can be used for tougher stains, being careful not to flood the surface.
- Abrasive rubbing of spots should be avoided, discoloration and delamination may occur.
- Great care should be taken in cleaning any dark colors because of the possibility of causing "light marks".
- Occasional vacuuming is acceptable and will help maintain look.
- Consult with a professional cleaning service for more difficult stains or when overall cleaning is needed.